

N6 • 001 • 02

Rolls-Royce
Silver Spirit
Silver Spur

Bentley
Mulsanne
Mulsanne Turbo

**Power Assisted Steering
Rack & Pinion Steering**

Car serial number


Silver Spirit & Bentley Mulsanne
SCAZS0000ACH01001 to 07355

Silver Spur
SCAZN0000ACH01006 to 07355

Bentley Mulsanne Turbo
SCBZS0T00BCH04233 to 07355

Parts marked thus * refer to Additional Information below

◁ Left-hand ▷ Right-hand



Additional Information

© Rolls-Royce Motors Limited 1984

Service Information sheet SZ/N6 should be read in conjunction with this schedule

* UR 22074 Complete assembly R.H.D. cars Refer to PSIS N3
UR 22075 Complete assembly L.H.D. cars before ordering

* CD 5954 .002 in. thick
CD 5955 .005 in. thick
CD 5956 .010 in. thick
CD 5957 .015 in. thick } as required

* RH 2696 Service kit. Basic
* RH 2726 Service kit. Supplementary

**Bentley
Mulsanne
Mulsanne Turbo
Eight**

Power Assisted Steering
Rack & Pinion Steering

Parts marked thus * refer to Additional Information below

◀ Left-hand ▶ Right-hand


Car serial number

Silver Spirit & Silver Spur
SCAZS0004DCX07356 to 24496 excluding
KCX23210 and KCH23213

Bentley Mulspanne
SCAZS0004DCX07356 to 13785

Bentley Mulspanne Turbo
SCAZS0004DCX07356 to 13804

Bentley Eight
SCBZS8004ECH08862 to 13835



Additional Information

**Service Information sheet SZ/N6
should be read in conjunction
with this schedule**

*** UR 26542 Complete assembly RHD cars Refer to PSIS N3**
UR 26543 Complete assembly LHD cars before ordering

*** RH 2696 Service kit basic**

* RH 2895 Service kit supplementary

* CD 5954 .002 in thick

CD 5955 .005 in thick as required

CD 5956 .010 in thick

CD 5957 .015 in thick

© Rolls-Royce Motors Limited 1984

**Power Assisted Steering
Rack & Pinion Steering**


Car serial number

Silver Spirit
From SCAZS00A6KCH23213, 24514 to 27798

Silver Spur
From SCAZN00A5KCX23210, 24516 to 27780

Parts marked thus * refer to Additional Information below

◁ Left-hand ▷ Right-hand



Additional Information

© Rolls-Royce Motor Cars Limited 1990

- * UR 70654 RH Drive cars
UR 70655 LH Drive cars
- * CD 5911 Supplied only with overhaul kit RH 2895
Not with RH 3001 service kit
- * CD 5954 .002 in thick
CD 5955 .005 in thick
CD 5956 .010 in thick
CD 5957 .050 in thick
as required
- * RH 3001 Service kit for rack

- * RH 3010 Overhaul kit for rack
- * CD 6556 Joint washer 0.005 in
CD 6557 0.002 in
CD 6558 0.006 in
CD 6559 0.010 in
as required

Car serial number

Turbo R
SCBZS0TOXFCH12834 to 23935 excluding
KCH23211, 23212, 23214, 23215, 23217,
23218, 23219

Bentley Eight
SCBZS8003GCX13876 to 24497

Bentley Mulsanne
SCAZS0006GCX13860 to 24501 excluding
KCX23216


Bentley Mulsanne L
SCAZN42A7GCX13873 to 24501 excluding
KCX23216

Bentley Mulsanne Turbo
SCBZN0T01GCH13928 to 14162

**Power Assisted Steering
Rack and Pinion Steering**

Parts marked thus * refer to Additional Information below

◁ Left-hand ▷ Right-hand



Additional Information

© Rolls-Royce Motors Limited 1984

* UR 27336 R.H. Drive cars Refer to PSIS N3
UR 27337 L.H. Drive cars before ordering

* CD 5911 Supplied only with make up kit RH 2726 not
supplied with RH 2696 Service kit

* CD 5954 .002 in thick
CD 5955 .005 in thick
CD 5956 .010 in thick
CD 5957 .015 in thick

as required

* RH 2696 Service kit
RH 2726 Make up kit containing CD 5911
CD 5926 (2)
CD 5934 (2)
CD 5958 (5)

Power Assisted Steering
Rack & Pinion Steering

Parts marked thus * refer to Additional Information below

◁ Left-hand ▷ Right-hand


Car serial number

Turbo R
From SCBZR04A0KCH23211, 23212, 23214,
23215, 23217, 23218, 23819, 24519 to 27793

Bentley Eight
From SCBZE00A8KCH24513 to 27799

Bentley Mulsanne S
From SCBZS02B3KCX23216. 24515 to 27796

Bentley Mulsanne L
From SCBZN00A2KCH24569 to 27775



Additional Information

- * UR 70708 RH Drive cars
- UR 70707 LH Drive cars
- * CD 5911 Supplied only with overhaul kit RH 2895
- Not with RH 3001 service kit

* CD 5954 .002 in thick
CD 5955 .005 in thick
CD 5956 .010 in thick
CD 5957 .050 in thick

} as required

- * RH 3001 Service kit for rack
- * RH 3010 Overhaul kit for rack

* CD 6556	Joint washer	0.005 in	
CD 6557		0.002 in	} as required
CD 6558		0.006 in	
CD 6559		0.010 in	

© Rolls-Royce Motor Cars Limited 1990