

M2 • 001•05

Rolls-Royce
Silver Spirit
Silver Spur

Bentley
Mulsanne
Mulsanne Turbo

Electrical System
Fuseboard Fittings and Relays

Car serial number


Silver Spirit & Bentley Mulsanne
SCAZS0000ACH01001 – SCAZS0007ECH10126

Silver Spur
SCAZN0000ACH01006 – SCAZN000XECX10127

Bentley Mulsanne Turbo
SCBZS0T00CCH04233 – SCBZS0T09ECH10099

Parts marked thus * refer to Additional Information below

◀ Left-hand ▶ Right-hand



Additional Information

© Rolls-Royce Motors Limited 1984

- *UD 24551 Direction Indicator flasher
- UD 24552 Hazard warning flasher
- *UD 19102 - 20 amp fuse
- *UD 11539 - 10 amp fuse
- *UD 4896 - Radio fuse 5 amp
- *UD 35186
- UD 22906 USA, Japan & Australia
- *UD 20991 USA only

- *UD 22869
- UD 25307 Division cars only
- *See fiche S46-001,2 Ref fuse board I.D. Label
- SPM 1405 Spacer, 10 amp fuse

Rolls-Royce	Bentley
Silver Spirit	Mulsanne
Silver Spur	Mulsanne Turbo
	Turbo R
	Eight


Electrical System
Fuseboard Fittings & Relays

Car serial number

- Silver Spirit & Bentley Mulsanne
SCAZS42A3FCX12001, 13859 to 13869 except 13860
- Silver Spur
SCAZN42A6FCX12002, 13873 to 13874
- Mulsanne Turbo
SCBZS0T08FCX12005, 13883 to 14162
- Bentley Eight
SCNBZS800XFCH12013 to 13835
- Turbo R
SCBZS0T0XFCH12834 to 13874

Parts marked thus * refer to Additional Information below

◀ Left-hand ▶ Right-hand



Additional Information

© Rolls-Royce Motors Limited 1984

- * UD 24551 Direction indicator flasher
- UD 24552 Hazard warning flasher
- * UD 19102 - 20 amp fuse
- * UD 11539 - 10 amp fuse
- * UD 4896 - Radio fuse 5 amp
- * UD 35186
- UD 22906 USA, Japan, and Australia
- * UD 20991 USA only
- * UD 22869
- UD 25307 Division cars only
- * See fiche S46-003 Ref fuse board I.D. label
- SPM 1405 Spacer, 10 amp fuse
- * UD 19103 Ice warning module Bentley Eight

M2·003·02

Rolls-Royce	Bentley
Silver Spirit	Mulsanne
Silver Spur	Turbo R
Silver Spur	Eight
Limousine	

Car serial number

Silver Spirit
From SCAZS0006GCX13860, 13870 to 16930

Silver Spur
From SCAZN42A7GCX13872, 13897 to 16970
(except SCAZN00004FCH14000 to 14025)

Mulsanne Turbo
From SCBZS0T09GCX13875 to 14162


Turbo R
SCBZS0T0XFCH12834 to 16570

Bentley Eight
From SCBZS8003GCH13876 to 16954

Electrical System
Fuse Board and Fittings

Parts marked thus * refer to Additional Information below

◀ Left-hand ▶ Right-hand



Additional Information

- * UD 26371 Part of loom assembly
- * UD 24551 Direction Indicator flasher
UD 24552 Hazard warning flasher
- * UD 35186
UD 22906 USA, Japan & Australia
- * UD 22869
UD 25307 Division cars only
- * UD 19103 Ice warning module
- * UD 20991 USA only

© Rolls-Royce Motors Limited 1984

Car serial number

Silver Spirit
SCAZS0002HCH20003 to 24496
except 23213

Silver Spur
SCAZN0009HCH20004 to 24503
except 23210


Mulsanne S
SCBZS0000HCH20013 to 24501
except 23216

Turbo R
SCBZS0T03HCX20001 to 23935
except 23211, 23212, 23214, 23215,
23217, 23218, 23219

Eight
SCBZS8009HCX20006 to 24497

Parts marked thus * refer to Additional Information below

◀ Left-hand ▶ Right-hand



Additional Information

© Rolls-Royce Motors Limited 1986

- * UD 26548 Other than Japan & Middle East or
UD 26537 Japan & Middle East
- * UD 19103 Turbo, Bentley Eight only
- * UD 70323 120 kph speed warning Middle East only or
UD 26692 Japan only
- UD 26553 Identification label - relays
- UD 26551 Identification label - relays
USA, Canada, Europe & Middle East
- UD 26554 Identification label - fuseboard
- UD 26632 Relay
- * UD 26371 Part of loom assembly

- * SPM 1708 Auto Fuse Connector for 1.5 mm cable
- UD 26155 Auto Fuse Connector for 2.5 mm cable
- UD 26372 Auto Fuse Connector for 0.5 mm cable
- * SPC 3448 or
SPM 1766
- * UD 70478 15 amp fuse ignition, Turbo cars

Part of
loom
assembly

Rolls-Royce	Bentley
Silver Spirit	Mulsanne
Silver Spur	Eight
Silver Spur	Turbo R
Limousine	

Parts marked thus * refer to Additional Information below


Car serial number

Silver Spur
SCAZN00A5KCX23210, 24516 to 27780

Mulsanne S
SCBZS02B3KCX23216. 24515 to 27796

Turbo R
SCBZR04A0KCH23211, 23212, 23214,
23215, 23217, 23218, 23219,
24519 to 27793

Eight
SCBZE00A8KCH24513 to 27799



© Rolls-Royce Motor Cars Limited 1991

UD 70975 Label Relays, Bentley cars for USA only
 *UD 70946 Diagnostic switch Turbo cars only
 *UD 26548 Other than Japan & Middle East or
 UD 26537 Japan & Middle East
 *UD 19103 Turbo, Bentley Eight only
 *UD 70323 120 kph speed warning Middle East only or
 UD 26692 Japan only
 UD 26632 Relay
 *UD 26371 Part of loom assembly

UD 26372 Auto fuse connector for 0.5 mm cableassembly
* SPC 3448 or
SPM 1766

*UD 71397 Label fuseboard (English)
UD 71398 Label fuseboard (French)
UD 71401 Label fuseboard, USA only
*UD 70924 Label Relays, UK, Australia & Japan RHD
UD 70923 Label Relays, Canada, Euro 1 & 2, Japan LHD
Middle East. USA cars other than Bentley

* SPM 1708 Auto fuse connector for 1.5 mm cablePart of
UD 26155 Auto fuse connector for 2.5 mm cableloom